



## AIR PRESSURE

Most instruments calibrated in Calibration Laboratory in the field of air pressure are electronic barometers, barographs and mechanical barometers in the range from 500 hPa to 1200 hPa. Degranges et Heut dead weight gauge is a pressure reference standard. Highly pure nitrogen combined with pressure regulator is used as a pressure medium. For less accurate measuring instruments, digital pressure gauges are used as the working standards.

Measured quantity	Range
Air pressure	500 hPa do 1200 hPa

Scope of accreditation is available at Slovenian accreditation web site:  
[http://www.slo-akreditacija.si/?s=lk-006&post\\_type=lpacreditation](http://www.slo-akreditacija.si/?s=lk-006&post_type=lpacreditation)