



Classification of results  
Level LDEN

<= 35.0 dB(A)	<= 70.0 dB(A)
<= 40.0 dB(A)	<= 75.0 dB(A)
<= 45.0 dB(A)	<= 80.0 dB(A)
<= 50.0 dB(A)	> 80.0 dB(A)
<= 55.0 dB(A)	
<= 60.0 dB(A)	
<= 65.0 dB(A)	

Ldvn  
00:00 - 24:00  
visina izracuna 4 m  
korak izracuna 4 m



Priloga: 4  
List : 4  
31.03.2026  
M 1: 4000

Karta hrupa  
poseg

Client  
Kolektor d.d.  
Vojkova ulica 10  
5280 Idrija

Auftragnehmer  
Marbo Okolje d.o.o.  
Finzgarjeva ulica 1A  
4248 Lesce